NC Department of Insurance Office of the State Fire Marshal - Engineering Division 1202 Mail Service Center, Raleigh, NC 27699-1202 919-661-5880

Water Closet In Type II Stall Locations

Code: 2002 Accessibility Code Date: December 14, 2004

Section: 11.4.2

Question:

Must the water closet in a Type II stall be located diagonally opposite the door?

Answer:

No, this applies to a Type I stall only (see 11.4. 1).