

**NC Department of Insurance
Office of the State Fire Marshal - Engineering Division
1202 Mail Service Center, Raleigh, NC 27699-1202
919-647-0000**

Lay-In Ceiling for Smoke Partition Continuity

Code: 2018 Building Code
Section: 710.4

Date: September 6, 2018

Question:

Is a lay-in ceiling system considered a ceiling membrane to “limit the transfer of smoke” as required by NC Building Code, Section 710.4?

Answer:

The ceiling is expected to be sealed as though it were a horizontal wall.

A lay-in ceiling that does not have the joint of each tile sealed with a material capable of remaining in place at 400⁰ Fahrenheit is not considered a continuous membrane and is not acceptable as complying with Section 710.4 for ceiling membrane constructed to limit the transfer of smoke.

A lay-in ceiling that does have the joint of each tile sealed with a material capable of remaining in place at 400⁰ Fahrenheit is considered a continuous membrane and is acceptable as complying with Section 710.4 for ceiling membrane constructed to limit the transfer of smoke. The joint where the ceiling system meets the wall as well as ceiling penetrations such as light fixtures and sprinkler heads must also be sealed as described above.

A fire-resistant-rated ceiling system is also acceptable as complying with Section 710.4 for ceiling membrane constructed to limit the transfer of smoke

Keywords:

acoustical, tile, ACT